

# STEREO IMPACT

PROBLEM REPORT

PR-2012

LET Housing Parts

6/2/2005

PR Numbers: 1xxx=UCB, 2xxx=Caltech/JPL, 3xxx=UMd, 4xxx=GSFC/SEP, 5xxx=GSFC/Mag,  
6xxx=CESR, 7xxx=Keil, 8xxx=ESTEC, 9xxx=MPAe

<b>Assembly:</b> SEP	<b>SubAssembly:</b> LET
<b>Component/Part Number:</b>	<b>Serial Number:</b> FM2
<b>Originator:</b> Branislav Kecman	<b>Organization:</b> Caltech
<b>Phone:</b> (626) 395-4264	<b>Email:</b> kecman@srl.caltech.edu

## Failure Occurred During (Check one )

- Functional test       Qualification test       S/C Integration       Launch operations

## Environment when failure occurred:

- Ambient       Vibration       Shock       Acoustic  
 Thermal       Vacuum       Thermal-Vacuum       EMI/EMC

## Problem Description

While reassembling FM2 LET sensor in order to apply corrective actions described in PFR 2006 & 2007, the tapped 0-80 holes in LET housing were found to be oversized and out of spec. The anomaly was evident on approximately 60-75% of the 0-80 holes in the LET housing. The running torque on new 0-80 screws with Poly-Lok feature alone wasn't sufficient, and there was unanimous fear that the proposed corrective action wouldn't work as planned.

## Analyses Performed to Determine Cause

Tapped holes in the LET housing parts were manufactured using "rolled" threads rather than "cut" threads. In the process of making "rolled" threads a larger drill size is used, so the resulting tapped hole size is larger than the specification allows. This was not noticed during GSFC's flight parts inspection, and by the time the problem was discovered it was too late to remake the parts.

## Corrective Action/ Resolution

- Rework       Repair       Use As Is       Scrap

Install new screws with the Poly-Lok feature and add a stripe of EC2216 epoxy on the threads to fill the voided areas and provide more strength to the screw. This corrective action was performed throughout the SEP Main Assembly (LET/HET/SEP Central) to assure there are no further issues during environmental testing. Recommended 3-axis vibe test was successfully completed between 7/12/2005 - 7/14/2005.

**Date Action Taken:** 6/3/2005 – 6/5/2005

**Retest Results:** Passed

**Corrective Action Required/Performed on other Units**  Serial Number(s): FM1 LET

Same steps were applied and 3-axis vibe test was successfully completed between 7/12/2005 - 7/14/2005.

## Closure Approvals

Subsystem Lead: Branislav Kecman \_\_\_\_\_ Date: 8/31/05 \_\_\_\_\_  
IMPACT Project Manager: \_\_\_\_\_ Date: \_\_\_\_\_  
IMPACT QA: \_\_\_\_\_ Date: \_\_\_\_\_  
NASA IMPACT Instrument Manager: \_\_\_\_\_ Date: \_\_\_\_\_